


Historic Asbestos
Contaminated Land





Identified Bat Roost



Identified Area
of Winter
Waterlogging



Identified
Bat Roost




Identified
Bat Roost




Identified
Badger
Sett




Giant Hogweed



Historic Asbestos
Contaminated Land




Identified Bat Roost



Identified Area
of Winter
Waterlogging



Identified
Bat Roost



Identified
Bat Roost

Identified
Badger
Sett

Giant Hogweed